






## Installation details

- Location:** The ice cream factory of Nestlé  
Kiryat Malachi, Israel  
froneri.co.il
- Model/area:**  S25 for the hot water tank.  
 S10 for the CIP (cleaning-in-place machines).
- Problem:** Very hard scale problems needed constant acids treatment.
- Result:** Due to the excellent results from Vulcan S25 running for 3 years, Vulcan S10 was introduced to solve the scale problems from the hot water piping in the CIP system.
- Installed by:** EYE-IN ELECTRONICS  
www.eye-in-electronics.co.il



Nestlé is a Swiss multinational food and drink processing conglomerate corporation headquartered in Switzerland. It is the largest food company in the world.

### Vulcan S25 treats the hot water tank



### Hot water tank




### Vulcan S10 treats the cleaning-in-place machines



Without Vulcan, the hot water pipe was blocked and the production had to be stopped to replace it. The Vulcan S10 was installed on the supply pipe and solved the problem.

### After 2 months



The container looks shiny and clean inside and outside. The filters at the entrance also stay clean. No more extra treatment since then.