



The Cooling System in the Poultry Farm



Installation details

- Location:** 3 chicken farms in Morocco
- Area:**
- 6 cooling systems
 - drinking water of hens
- Model:**  Vulcan S10
- Result:** After Vulcan S10 had been installed for 2 weeks, scale had been softer and easily removed with a water gun.
- Installed by:** STE ETCT INDUSTRIE



Vulcan S10 was installed in the water main to treat 6 cooling systems in 3 chicken farms.



Without any water treatment, scale was hard like stones.



After Vulcan S10 had been installed for 2 weeks, scale had been softer and easily removed with a water gun.